

HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

MINIDOKA RELOCATION CENTER WAREHOUSE

HABS ID-131

(American Falls Reservoir District Warehouse)

111 South Fir Street

Shoshone

Lincoln County

Idaho

HABS photographs ID-131-1 through ID-131-11 are large-format views of the Minidoka Relocation Center Warehouse currently owned by the Bureau of Reclamation and in use by American Falls Reservoir District No. 2 (AFRD). Historic photographs of this building and engineering or architectural drawings have not been found. For additional narrative and photographic documentation about this building, please refer to HABS Report ID-131. The photographs are arranged to show each facade and its details in turn, beginning with the south side, and ending with views of the interior.

INDEX TO BLACK AND WHITE PHOTOGRAPHS

Dave Walsh, photographer, September 2004

- | | |
|----------|---|
| ID-131-1 | AFRD WAREHOUSE, SOUTH SIDE. FACING NORTH. METAL AWNING ALONG LENGTH OF BUILDING AND VERTICAL METAL SIDING ARE ALTERATIONS MADE BY THE AFRD. |
| ID-131-2 | AFRD WAREHOUSE, SOUTH SIDE DETAIL, SLIDING DOORS. FACING NORTH. COMPARE WITH FIGURES 4 AND 5 IN NARRATIVE REPORT, WHICH SHOW DIAGONAL BRACES BELOW GLAZED SECTION OF DOORS. |
| ID-131-3 | AFRD WAREHOUSE, WEST SIDE, FACING EAST. NOTE PLACEMENT OF METAL SIDING BETWEEN THE TWO HALVES OF THE SLIDING DOOR. ORIGINAL 8-PANE WINDOW HAS BEEN REPLACED BY A SINGLE PANE OF GLASS. CONCRETE BRICK CHIMNEY IS AT LEFT OF VIEW. |

MINIDOKA RELOCATION CENTER WAREHOUSE

HABS ID-131

INDEX TO PHOTOGRAPHS

ID-131-4	AFRD WAREHOUSE, WEST SIDE DETAIL OF ALTERED SLIDING DOORS, FACING EAST. WEATHER COVER OVER RAIL IS ORIGINAL. SHEET METAL SIDING HAS BEEN INSERTED BETWEEN TWO HALVES OF SLIDING DOORS.
ID-131-5	AFRD WAREHOUSE, OBLIQUE VIEW OF WEST AND SOUTH SIDES.
ID-131-6	AFRD WAREHOUSE, NORTH SIDE, FACING EAST.
ID-131-7	AFRD WAREHOUSE, EAST SIDE, FACING WEST. NOTE LEAN-TO AFFIXED TO WALL AND THREE SETS OF TRIPLE-BANK WINDOWS.
ID-131-8	AFRD WAREHOUSE, EAST SIDE DETAIL SHOWS CONNECTION OF LEAN-TO TO WALL. FACING WEST. NOTE THE PROFILE OF THE METAL AWNING ON SOUTH SIDE. ELECTRICAL CONDUIT AND OTHER SERVICES PENETRATE WALL. POLE SECURED WITH TRIANGULAR BRACES AT CORNER IS COMMUNICATION POLE.
ID-131-9	AFRD WAREHOUSE, INTERIOR, FACING WEST. TWO ROWS OF ORIGINAL WOOD POSTS SUPPORT CEILING RAFTERS. SHEETROCK ON CEILING AND WALLS IS AN ALTERATION MADE BY THE AFRD. LOFT NEAR CENTER OF VIEW MAY HAVE BEEN PART OF THE ORIGINAL BUILDING.
ID-131-10	AFRD WAREHOUSE, INTERIOR, FACING SOUTHEAST TOWARD SOUTHEAST CORNER. SHEET ROCK ON CEILING. RAFTERS ARE SUPPORTED BY POST.
ID-131-11	AFRD WAREHOUSE, INTERIOR DETAIL OF RAFTER SUPPORT POST TIMBER AND METHOD OF BRACING. THE BRACES PENETRATE THE SHEET ROCK, SUGGESTING THAT THESE ARE ORIGINAL.